

AIR POLLUTION CONTROL DIVISION
FIELD INSPECTION REPORT

NAME UGS Lead
(Company or Individual)

Plant ID No. _____

ADDRESS _____

CITY East Chicago IN Zip Code _____

COUNTY _____

Inspected by HOWEARS
Date 4/18/85
Reported by HOW
Date 5/2/85

COMPLAINT INVESTIGATION YES _____ NO ☒ COMPLAINT NO. _____

COMPLAINANT AND ADDRESS Sony Traicoff, Mtn Deger & Ron Holden Mgrs/Prod

PERSONS INTERVIEWED _____

RIGHT OF ENTRY WAS GRANTED BY Ronald Holden, Mgr of Prod

OBJECTIVES, SUMMARY OF FINDINGS AND RECOMMENDATIONS:

The high levels of Pb in the soil around the plant and a mtg to Federal & Local officials on 4/19 precipitated the inspection of the plant. We saw a number of areas where there were problems:

- Many piles of mat'l that were scoured by wind
- Dust on nearly all drives to vehicle traffic
- which were a source of wind-blown emissions crossing the ^{overpasses} ~~highways~~
- Handling of collected dust from baghouses was not satisfactory.
- street sweeper was not adequately ^{cleaning} ~~collecting~~ the roads, (although it was not seen in operation)

The company was told that it was our opinion they were violating 325/AC 6-4. This statement was also stated to the Comp. Atty Robt Steinwertzel.

EPA Region 5 Records Ctr.



308181